

PLOT DATE: January 13, 2022
FILE PATH: W:\data 09\092020\Drawings\Final\Phase - 3 & 4\Exhibits\PH 4 Tree Removal\EXH - PH 4 Tree Removal.dwg




Trees to be Removed	
Tree #	
127	191
128	193
129	194
133	195
134	196
135	197
137	198
138	199
139	200
141	201
142	202
143	203
144	204
145	205
146	206
148	207
149	208
150	209
151	210
152	211
183	212
185	213
186	214
187	228
188	229
189	230
190	231
	234
Total:	55

TREE NUMBERS CORRESPOND TO THE BIOTIC
EVALUATION REPORT PREPARED BY LIVE OAK
ASSOCIATES, INC., ON MARCH 8, 2012.

LEGEND

-  EXISTING TREE TO REMAIN
-  EXISTING TREE TO BE REMOVED



EXISTING TREE REMOVAL
SAN SEBASTIAN PHASE 4

MORGAN HILL, CALIFORNIA

JANUARY 2022

RJA
RUGGERI-JENSEN-AZAR
ENGINEERS • PLANNERS • SURVEYORS
8055 CAMINO ARROYO GILROY, CA 95020
PHONE: (408) 848-0300 FAX: (408) 848-0302

JOB NUMBER: 092030

SHEET 1 OF 1